

# Oil Field Environmental Incident Summary

**Incident:** 20160108124750      **Date/Time of Notice:** 01/08/2016 12:47

**Responsible Party:** XTO ENERGY INC.

**Well Operator:** XTO ENERGY INC.

**Well Name:** WARD 11X-23

**Field Name:** CHARLSON

**Well File #:** 18510

**Date Incident:** 1/7/2016      **Time Incident:** 16:15

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 154

**Rng:** 95

**Sec:** 23

**Qtr:** NW NW

**Location Description:** Fluid misted east off location onto landowner property affecting an area approximately 390' x 300'.

**Submitted By:** JORDAN WOLF

**Received By:**

**Contact Person:** KAYLAN DIRKX  
P.O Box 6506  
321 22ND AVE E  
WILLISTON, ND 58801

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Stuffing Box Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units
Oil	2	Barrels

Recovered	Units
-----------	-------

Followup	Units
2	barrels

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 3/24/2016

**Clean Up Concluded:** 1/25/2016

**Risk Evaluation:**

None- well was shut in at time of discovery and no injuries occurred.

**Areal Extent:**

East off location onto landowner property affecting an area approx. 390' x 300'.

**Potential Environmental Impacts:**

Minimal- Well pad soil was affected on location. Fluid misted east off the pad, snow and minimal vegetation impact was observed.

**Action Taken or Planned:**

The well was shut in immediately at the time of discovery. Cleanup of affected facility soil and off pad area will begin as soon as the One Call clears. The stuffing box rubbers were replaced and the stuffing box was inspected.

**Wastes Disposal Location:** Any impacted material will be hauled to an approved disposal facility (R360).

**Agencies Involved:****Updates**

---

**Date:** 1/8/2016     **Status:** Reviewed - Follow-up Required

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the release misted off of the east side of the well pad. Further followup is needed.

---

**Date:** 1/13/2016     **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

1/13/2016 at 14:00, on location. Large area off location has been scraped; area consists of native grasses/CRP land. No visible staining within scraped area. Faint staining east of scraped area should naturally attenuate. Check in spring to monitor recovery of scraped land.

---

**Date:** 5/5/2016      **Status:** No Further Action Requested

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location at 1515. Inspected site. Grass looks healthy and growing. No further up needed.

---

**Date:** 6/2/2016      **Status:** Correspondence

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Taylor Souder sent a No Further Action letter dated June 2, 2016.